

Facility Safety Inspection

Fire & Life Safety / Environmental Health

Licensed Day Care Programs

Compliance Plan

Provider's Name: **EmBe South Child Care Center** City: **Sioux Falls**

Provider Number: **010605399**

Inspector: **Kenneth
Anderson**

Date of Inspection: **06/28/2018**

Time of Inspection: **12:23 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

Corrections To Be Made:

The SW exit of the Gym is blocked by a container. Container must be removed to allow for 36 inch exit clearance.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

06/28/2018

Actual
Completion
Date:

07/23/2018

Status: **Corrected**

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:

There are rooms that have combustible materials less than 18 inches from the ceiling. Rooms: Transitions, Two-A, Two-B, Pre K-B, Jr. Kinder, Kinder College and the Gym Storage Room.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

06/30/2018

Actual
Completion
Date:

07/23/2018

Status: **Corrected**

15. Is electrical system being used properly? 61:15:01 NOTE: Check for overloads or frayed extension cords.

Corrections To Be Made:

**There is a 3-way plug-in plugged into a single outlet in the Pre K-B Room.
There needs to be a power strip there.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

06/29/2018

Actual
Completion
Date:

07/23/2018

Status: **Corrected**

B. ENVIRONMENTAL HEALTH

22. Does the construction of walls, ceilings, doors, window and skylights appear clean and in good repair?
Does outside appearance and construction appear in good repair? 67:42:11:39

Corrections To Be Made:

**In Infant Rooms 1&2 the walls are showing inside of the wall material.
Walls to be in good repair.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

07/07/2018

Actual
Completion
Date:

07/23/2018

Status: **Corrected**

Latorid Horan

Provider Signature

06/28/2018

Date

Kenneth Anderson

Inspector Signature

06/28/2018

Date