## Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: Discovery Learning Center City: Sioux Falls Provider Number: 018042494

Inspector: Elijah Ehresmann Date of Inspection: 01/08/2019 Time of Inspection: 12:45 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

10. If providing care for children under 5 years of age, are there self-closing, or tamper resistant childproof electrical covers on all outlets? 67:42:11:10

Corrections To Be Made:

The northeast rooms in the lower level do not have self closing or tamper resistant outlets.

Agency Action:

Compliance Plan

Suggested Actual

\*\*\*The outlets have been replaced with self-closing outlets.

Completion
Date:

Completion
Date:

02/08/2019 01/31/2019

Status: Corrected

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

Corrections To Be Made: Agency Action:

The south exit by bathrooms on main level has a babygate blocking the Compliance Plan

\*\*\* The baby gate is not being utilized, which allows the door to remain unblocked.

Suggested Completion Completion Date: Date:

02/08/2019 01/31/2019

Status: Corrected

13. In areas providing access to exits, do combustible decorations cover less than 10% of the wall area? 61:15:05:05

Corrections To Be Made:

Agency Action:

The northeast lower level rooms have paper covering the doors.

**Compliance Plan** 

\*\*\*The decorative paper has been removed from the classroom doors.

Suggested Completion Date:

Actual Completion Date:

02/08/2019

01/31/2019

Status: Corrected

## **B. ENVIRONMENTAL HEALTH**

22. Does the construction of walls, ceilings, doors, window and skylights appear clean and in good repair? Does outside appearance and construction appear in good repair? 67:42:11:39

Corrections To Be Made:

\*\*\*The hole in the wall has been repaired.

Agency Action:

Repaired hole by bathrooms on main level needs to be finished.

**Compliance Plan** 

Suggested Completion

Actual Completion Date:

Date:

02/08/2019 01/31/2019

Status: Corrected

25. Is there at least 3 feet of space between napping children to help prevent the spread of communicable diseases? 67:42:11:05 NOTE: Stackable cribs are not allowed.

Corrections To Be Made:

Agency Action:

Observed napping children sleeping within 3 feet of other children.

Compliance Plan

\*\*\*The children are placed three feet apart during nap time. In addition, the children sleep with their heads and feet alternating to create more distance between the children to prevent the spread of germs.

Suggested Actual Completion Date:

Completion Date:

02/08/2019 01/31/2019

Status: Corrected

37. Are toilet rooms and fixtures clean and in good repair? 67:42:11:06

Corrections To Be Made: Agency Action:

The hole above the toilet in the basement bathroom needs to be repaired. Compliance Plan

\*\*\*The hole in the wall has been repaired.

Suggester

Suggested Completion Date:

Actual Completion Date:

02/08/2019

01/31/2019

Status: Corrected

50. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made:

Furnace has not been inspected within the last year.

\*\*\*Documentation has been provided to Child Care Services with the current inspection of the heating and cooling system.

Agency Action:

**Compliance Plan** 

Suggested Completion Date:

Actual Completion Date:

02/08/2019

02/06/2019

Status: Corrected

## C. FOOD SERVICE

74. Do employees wash hands after use of restroom, changing a diaper, working with soiled clothing/linens, and before handling food? 67:42:11:33

Corrections To Be Made:

Agency Action:

Handwash sink in kitchen has hose attached to faucet; therefore, people cannot effectively wash hands before handling food.

\*\*\*A splitter has been installed on the handsink in the kitchen to allow for the cook to wash their hands and also to attach a hose to fill the mop bucket. Compliance Plan

Suggested Completion Date: Actual Completion Date:

02/08/2019

01/31/2019

Status: Corrected

Corrections To Be Made:

Cupboards in the kitchen have chips and exposed wood.

\*\*\*A filler and waterproof paint have been applied to the kitchen cupboards to treat the chips and exposed wood.

Suggested Completion Date:

O2/08/2019

O1/31/2019

Status: Corrected

Elijah Ehresmann

Inspector Signature

01/08/2019

Date

91. Are food contact surfaces free of breaks, open seams, cracks, chips, pits and other similar

imperfections, difficult-to-clean corners and crevices? 67:42:11:07

01/08/2019

Date

**Cadet Hoxsie** 

Provider Signature