Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: First Adventure Learning City: Sioux Falls Provider Number: 018042656

Center

Inspector: Michael Date of Inspection: 02/19/2020 Time of Inspection: 2:50 PM

Czmowski

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:

In the First Step Preschool 1-bathroom, combustible material was stored less than 18 inches below the sprinkler heads.

Combustible material must be stored at least 18 inches below the sprinkler

head deflectors.

Correction: Combustible material has been moved so it at least 18 inches below sprinkler head deflectors.

Agency Action:

Compliance Plan

Suggested Completion Date:

Actual Completion Date:

02/20/2020

03/25/2020

Status: Corrected

B. ENVIRONMENTAL HEALTH

22. Does the construction of walls, ceilings, doors, window and skylights appear clean and in good repair? Does outside appearance and construction appear in good repair? 67:42:11:39

Corrections To Be Made:

In the First Step Preschool 2 bathroom, the wall was not in good repair. The First Step Preschool restroom ceiling air vents, restroom exhaust vent and ceiling tiles appear dusty.

The walls and ceilings must be clean and in good repair.

Correction: The wall in the First Step Preschool 2 bathroom has been repaired. All ceiling air vents, restroom exhaust vents and ceiling tiles have been cleaned.

Agency Action:

Compliance Plan

Suggested Completion Date:

Actual Completion Date:

03/19/2020

03/25/2020

Status: Corrected

26. Are cribs and mattresses maintained in good repair? 67:42:11:05

Corrections To Be Made:

In the First Step Preschool 1, there were several nap mats that were not in good repair.

The nap mats must be maintained in good repair.

Correction: All nap mats that were not in good repair have been replaced.

Agency Action:

Compliance Plan

Suggested Completion Date:

Actual Completion Date:

03/19/2020

03/25/2020

Status: Corrected

39. Is there a supply of hand soap and single use towels or an air dryer provided in each bathroom facility? 67:42:11:33

Corrections To Be Made:

In the Pre-Kindergarten restroom, single use towels were not present during the inspection.

Hand soap and single use towels must be available in each bathroom facility.

Correction: Single use towels were replaced immediately. Staff will monitor and replace the single use towels when running low.

Agency Action:

Compliance Plan

Suggested Completion Date:

Actual Completion Date:

02/21/2020

02/19/2020

Status: Corrected Immediately

C. FOOD SERVICE

80. Are potentially hazardous foods requiring cooking, cooked to heat all parts of the food to a temperature of at least 140 degrees F and held at that temperature until served or immediately refrigerated at 41 degrees F or below? 67:42:11:16

Corrections To Be Made:

The refrigerator temperatures in the upright kitchen refrigerator measured at 43.7 degrees F and in the young infant refrigerator measured at 50.1 degrees F at the time of the inspection.

The refrigerator temperatures must be maintained 41 degrees or lower.

Correction: The refrigerator temperature measured at 41 degrees. Staff will monitor the refrigerator temperature to ensure that is maintained 41 degrees or lower.

Agency Action:

Compliance Plan

Suggested Completion Date:

Actual Completion Date:

02/21/2020

03/25/2020

Status: Corrected

Kelli Jurgensen	02/19/2020	Michael Czmowski	02/19/2020
Provider Signature	Date	Inspector Signature	Date