## Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name:	B&G CLUB 57TH ST. LEARNING CENTER	City:	Sioux Falls	Provider Number:	018042257
Inspector:	Michael Czmowski	Date of Inspection:	08/18/2020	Time of Inspection:	2:28 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

11. Are exit signs provided over each exit, and where necessary to identify a change in the direction of egress travel? 61:15:05:05 NOTE: Exit signs must be interior or exterior illuminated or self-luminous.

Corrections To Be Made:	Agency Action:	
Exit emergency light combinations will not illuminate when testing battery backup. Exit lighting to be functional. *All batteries replaced and lights functional as of 10/05/2020	Compliance PlanSuggestedActualCompletionCompletionDate:Date:	
	08/31/2020	10/05/2020
	Status: Corrected	

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:	Agency Action:	
Combustible materials to be stored at least 2 feet below the ceiling in the 2 yr old restroom, restroom outside 2 B room and preschool restroom. *Items observed to be moved on 09/18/2020	Compliance Plan Suggested Completion Date:	Actual Completion Date:
	08/20/2020	09/18/2020
	Status: Corrected	

## **B. ENVIRONMENTAL HEALTH**

44. Is the water temperature at children's hand washing sinks maintained at 120 degrees or lower? 67:42:11:09

Corrections To Be Made:	Agency Action:		
Observed hot water temps at 121.3 degrees F in children restroom outside of Two B room. Water temperature to be no more than 120 degrees. *Water temperature measured at less than 120 degrees on 09/18/2020	Compliance Plan		
	Suggested Completion Date:	Actual Completion Date:	
	08/23/2020	09/18/2020	
	Status: Corrected		

50. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made:	Agency Action:		
Documentation of HVAC inspection to be available.	Compliance Plan		
*Inspection completed on 10/06/2020	Suggested Completion Date:	Actual Completion Date:	
	08/31/2020	10/06/2020	
	Status: Corrected		

## C. FOOD SERVICE

80. Are potentially hazardous foods requiring cooking, cooked to heat all parts of the food to a temperature of at least 140 degrees F and held at that temperature until served or immediately refrigerated at 41 degrees F or below? 67:42:11:16

Corrections To Be Made:	Agency Action:	
Temperature to be no more than 41 degrees in refrigerator in toddler room. At the time of the inspection, the temperature was 44 degrees. *Temperature observed at 41 degrees on 09/18/2020	Compliance Plan Suggested Completion Date:	Actual Completion Date:
	08/21/2020 Status: Corrected	09/18/2020

Bridget Hanson

08/18/2020

Michael Czmowski

08/18/2020

Provider Signature

Date

re