Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: Tiger Tots Childcare and City: Harrisburg Provider Number: 018042435

Preschool

Inspector: Kenneth Date of Inspection: 06/26/2018 Time of Inspection: 12:11 PM

Anderson

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

1. Are written emergency evacuation plans posted? 67:42:10:18

Corrections To Be Made: Agency Action:

There are rooms without a visible evacuation plan posted. Rooms: Compliance Plan Mobiles and Tobiles.

Suggested Actual
Completion Completion
Date: Date:

06/27/2018 07/17/2018

Status: Corrected

10. If providing care for children under 5 years of age, are there self-closing, or tamper resistant childproof electrical covers on all outlets? 67:42:11:10

Corrections To Be Made: Agency Action:

There are rooms with out child proof barrier on the outlets. Infant room (fan) and the toddlers.

Compliance Plan

Suggested Actual
Completion Completion
Date: Date:

06/29/2018 07/17/2018

Status: Corrected

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

Corrections To Be Made:

Agency Action:

In the infant sleeping room the exit to the outside is blocked by cribs. This door effects the infant room and the Mobiles room.

Compliance Plan

The Play Room door that exits to the outside directly is barred shut tight by gorrilla tape.

Suggested Completion Date:

Status: Corrected

Actual Completion Date:

The direct outside exit from the Preschool room is blocked by a large cart with items on it.

06/27/2018

07/17/2018

The east hallway outside exit door between the Preschool Room and the Tobiles Room is narrowed by toys and a play rug up to 12 inches. Exit

must be 36 inches.

The Infant Play Room, the direct outside door is blocked by infant play carts and swings. There is no egress opening.

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:

Agency Action:

In the Pre-K Room there are totes stored on top of cabinets. The distance from the top of the totes to the ceiling is 12 inches.

Compliance Plan

In the Toddler room there are items 5 inches from the ceiling.

Suggested Completion Date:

Actual Completion Date:

Combustible items must be stored 2 ft. below the ceiling or 18 inches below sprinkler heads.

06/30/2018

08/02/2018

Status: Corrected

B. ENVIRONMENTAL HEALTH

31. Is the diaper table sanitized after each use with an approved sanitizer (1600 PPM)? 67:42:11:06.01

Corrections To Be Made: Agency Action: **Compliance Plan** The toddler room diaper changing station sanitizer was at 100 PPM. Suggested Actual The infant room diaper changing station-one sanitizer bottle was at 0 PPM Completion Completion and the other was at 100 PPM Date: Date: Diaper changing area must be santized with an approved sanitizer (1600 06/26/2018 07/17/2018 PPM) Status: Corrected 50. Is the heating and cooling system maintained and inspected annually? 67:42:11:12 Corrections To Be Made: Agency Action: **Compliance Plan** Documentation of annual HVAC inspection to be provided.

Suggested

Completion

06/30/2018

Status: Corrected

Date:

Actual

Date:

Completion

08/02/2018

Brook Braun06/26/2018Kenneth Anderson06/26/2018Provider SignatureDateInspector SignatureDate