

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Apple Tree North**

City: **Sioux Falls**

Provider Number: **010605672**

Inspector: **Brian DeShazer**

Date of Inspection: **01/09/2019**

Time of Inspection: **5:01 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:	Agency Action:	
E07 closet going to the outside play area has combustible materials stored less than 2 feet from the ceiling.	Compliance Plan	
Combustible materials have been removed within 2 feet from the ceiling.	Suggested Completion Date:	Actual Completion Date:
	01/16/2019	01/15/2019
	Status: Corrected	

April Johannsen

01/09/2019

Provider Signature

Date

Brian DeShazer

01/09/2019

Inspector Signature

Date