## Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: Apple Tree East City: Sioux Falls Provider Number: 010605673

Time of Inspection: 11:26 AM

Date of Inspection: 06/14/2018

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

Inspector: Charles Anderson

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made: Agency Action: **Compliance Plan** In the Pre-K room, there is a shelf above the board with the solar system. Requirements for shelving with sprinklers is 18 inch clearance between Suggested Actual combustable items and the ceiling. Please remove the tote of shirts on that Completion Completion shelf as that is combustable. Date: Date: 07/14/2018 07/05/2018 Status: Corrected Lisa Carson 06/14/2018 **Charles Anderson** 06/14/2018 Provider Signature Date Inspector Signature Date