

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **YMCA Youth Development Center**

City: **Aberdeen**

Provider Number: **011008567**

Inspector: **Clint Rux**

Date of Inspection: **08/06/2018**

Time of Inspection: **2:00 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

13. In areas providing access to exits, do combustible decorations cover less than 10% of the wall area?
61:15:05:05

<p>Corrections To Be Made:</p> <p>The door of the Lollipop room had paper decorations covering the entire door. This must not exceed 10%.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">08/15/2017</td> <td style="text-align: center;">08/21/2018</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	08/15/2017	08/21/2018
Suggested Completion Date:	Actual Completion Date:				
08/15/2017	08/21/2018				

Kayley Johson

Provider Signature

08/06/2018

Date

Clint Rux

Inspector Signature

08/06/2018

Date