Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: YMCA Youth Development City: Aberdeen Provider Number: 011008567

Center

Inspector: Clint Rux Date of Inspection: 02/19/2019 Time of Inspection: 1:30 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

10. If providing care for children under 5 years of age, are there self-closing, or tamper resistant childproof electrical covers on all outlets? 67:42:11:10

Corrections To Be Made:

In the Professor's room there is a multi-plug outlet adapter under the smart board that does not have self-closing outlets. This outlet adapter should have self-closing adapters, or not be used. The outlet adapter was removed from the room and is no longer used.

Agency Action:

Compliance Plan

Suggested Actual
Completion Completion
Date: Date:

02/28/2019 03/01/2019

Status: Corrected

13. In areas providing access to exits, do combustible decorations cover less than 10% of the wall area? 61:15:05:05

Corrections To Be Made:

The door to the Wizard's room was covered with paper. This should not exceed 10% of the door area. The paper decorations were removed from the door so it's less than 10% covered.

Agency Action:

Compliance Plan

Suggested Actual
Completion Completion
Date: Date:

02/28/2019 03/01/2019

Status: Corrected

B. ENVIRONMENTAL HEALTH

Kayley Johnson

Provider Signature

30. If caring for infants, is there a diaper-changing table, properly constructed & maintained with smooth non-absorbent top? 67:42:11:06.01

Corrections To Be Made:	Agency Action:	
In the Oz room the diaper changing pad had a tear in the top. This should be replaced. A picture was provided of the new diaper changing pad.	Compliance Plan	
	Suggested Completion Date:	Actual Completion Date:
	02/28/2019	03/01/2019
	Status: Corrected	

02/19/2019

Date

Clint Rux

Inspector Signature

02/19/2019

Date