Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - Non-School Location Compliance Plan

Provider's Name: Great After School Place - City: Brookings Provider Number: 011516510

Peace Lutheran

Inspector: Charles Schmidt Date of Inspection: 07/08/2020 Time of Inspection: 9:17 AM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

11. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

Corrections To Be Made: Agency Action:

Exit from dining/kitchen area blocked. Clear exit pathway. Compliance Plan

Suggested Actual Completion Completion Date: Actual

07/10/2020 07/08/2020

Status: Corrected

B. ENVIRONMENTAL HEALTH

Corrected at time of inspection

21. Does the construction of walls, ceilings, doors, window and skylights appear clean and in good repair? 67:42:11:39

	Corrections To Be Made:			Agency Action:	
	Storage rooms have exposed framing etc.			Compliance Plan	
	Storage rooms referred to a	re not being used by GAP p	rogram.	Suggested Completion Date:	Actual Completion Date:
				07/31/2020	07/10/2020
				Status: Correcte	d
45.	Are dining tables sanitized before & after each meal with a solution of one ounce household bleach to wo gallons of water? 67:42:11:07				
	Corrections To Be Made:			Agency Action:	
	Bleach concentration too low.			Compliance Plan	
	Staff are aware of the correct mixing solution and will use moving forward.			Suggested Completion Date:	Actual Completion Date:
				07/31/2020	07/10/2020
				Status: Correcte	d
Shay So	orlie	07/08/2020	Charles Schmid	t	07/08/2020
Provider Signature		Date	Inspector Signatu	Inspector Signature	