## Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: Fit-n-Fun City: Rapid City Provider Number: 016598583

Inspector: Ann Marie Sailer Date of Inspection: 07/29/2020 Time of Inspection: 11:29 AM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

Corrections To Be Made:

Northwest exit door in the toddlers room has a curtain that needs to be removed. All exit doors must be maintained in a safe manner.

\*The shower curtain was removed per the director.

Agency Action:

Compliance Plan

Suggested Actual
Completion Completion
Date: Date:

08/12/2020 08/31/2020

Status: Corrected

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:

Storage is too close to sprinkler heads in the office storage room. Storage materials need to be at least 2 feet below the ceiling or 18 inches below the sprinkler head deflectors.

\*The office area was cleaned and the storage items are now 18 inches below sprinkler heads.

Agency Action:

**Compliance Plan** 

Suggested Actual
Completion Completion
Date: Date:

08/12/2020 08/31/2020

Status: Corrected

Huda Jabar	07/29/2020	Ann Marie Sailer	07/29/2020
Provider Signature	Date	Inspector Signature	Date