

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **LATI Childrens Educare Center** City: **Watertown**

Provider Number: **017508203**

Inspector: **Kelly Gnat**

Date of Inspection: **06/13/2019**

Time of Inspection: **2:22 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

66. Is playground equipment properly installed and maintained in good repair? Are sandboxes free from animal excrement and do they permit drainage? 67:42:11:02

<p>Corrections To Be Made:</p> <p>The metal plate at the top of the slide of the outdoor play structure is cracked. The metal plate needs to be repaired or replaced to prevent a child from getting injured.</p> <p>***The metal plate has been temporarily corrected with duct tape. There are plans to replace the play structure within the next couple months.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">07/12/2019</td> <td style="text-align: center;">07/08/2019</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	07/12/2019	07/08/2019
Suggested Completion Date:	Actual Completion Date:				
07/12/2019	07/08/2019				

Michelle York

Provider Signature

06/13/2019

Date

Kelly Gnat

Inspector Signature

06/13/2019

Date