

# Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - Non-School Location Compliance Plan

Provider's Name: **My Tea Tykes**

City: **Tea**

Provider Number: **018042238**

Inspector: **Elijah Ehresmann**

Date of Inspection: **10/10/2019**

Time of Inspection: **4:17 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## B. ENVIRONMENTAL HEALTH

27. Are toilet rooms and fixtures clean and in good repair? 67:42:11:06

<p>Corrections To Be Made:</p> <p><b>The stall wall in the men's bathroom is rusting across the bottom. *Wall repair observed on 11-12-2019.</b></p>	<p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>11/10/2019</b></td> <td style="text-align: center;"><b>11/12/2019</b></td> </tr> </table> <p>Status: <b>Corrected</b></p>	Suggested Completion Date:	Actual Completion Date:	<b>11/10/2019</b>	<b>11/12/2019</b>
Suggested Completion Date:	Actual Completion Date:				
<b>11/10/2019</b>	<b>11/12/2019</b>				

**Reahl Kunkle**

**10/10/2019**

Provider Signature

Date

**Elijah Ehresmann**

**10/10/2019**

Inspector Signature

Date