

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Sioux Falls Christian School** City: **Sioux Falls** Provider Number: **018042354**
 Inspector: **Dwight Johnson** Date of Inspection: **06/24/2019** Time of Inspection: **9:30 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

50. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

<p>Corrections To Be Made:</p> <p>Documentation of heating and cooling system inspection to be provided. *Documentation received on 07/31/2019.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">07/24/2019</td> <td style="text-align: center;">07/31/2019</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	07/24/2019	07/31/2019
Suggested Completion Date:	Actual Completion Date:				
07/24/2019	07/31/2019				

Shelby Vissia

 Provider Signature

06/24/2019

 Date

Dwight Johnson

 Inspector Signature

06/24/2019

 Date