

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Sioux Falls Christian School**

City: **Sioux Falls**

Provider Number: **018042354**

Inspector: **Dwight Johnson**

Date of Inspection: **10/07/2020**

Time of Inspection: **2:40 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

<p>Corrections To Be Made:</p> <p>-Decorations suspended from the ceiling are not compliant with the minimum distance requirements in proximity to the ceiling or the bottom of the sprinkler head. Must be suspended with nylon string. *Hanging item has been removed as of 10/15/2020</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">10/14/2020</td> <td style="text-align: center;">10/15/2020</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	10/14/2020	10/15/2020
Suggested Completion Date:	Actual Completion Date:				
10/14/2020	10/15/2020				

B. ENVIRONMENTAL HEALTH

50. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made:

-No verification of the system inspection can be produced at this time of compliance inspection.

***Documentation received on 10/14/2020**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

11/07/2020

Actual
Completion
Date:

10/14/2020

Status: **Corrected**

Bre Johnson

Provider Signature

10/07/2020

Date

Dwight Johnson

Inspector Signature

10/07/2020

Date