

# Facility Safety Inspection

## Fire & Life Safety / Environmental Health

### Licensed Day Care Programs

### Compliance Plan

Provider's Name: **Building Blocks CC and LC**

City: **Brandon**

Provider Number: **018042534**

Inspector: **Clint Rux**

Date of Inspection: **03/07/2019**

Time of Inspection: **9:00 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

#### A. FIRE AND LIFE SAFETY

9. If a fire sprinkler system is present in the building, is it operational? 61:15:05:09 NOTE: Valves are open, observe pressure gauge reading and sprinkler head condition.

Corrections To Be Made:

**The sprinkler system was last inspected on 9/11/17. This needs to be done annually.**

**\*Inspection completed on 03/07/2019.**

Agency Action:

**Compliance Plan**

Suggested  
Completion  
Date:

**03/21/2019**

Actual  
Completion  
Date:

**03/07/2019**

Status: **Corrected**

13. In areas providing access to exits, do combustible decorations cover less than 10% of the wall area? 61:15:05:05

Corrections To Be Made:

**Curtains were covering the exit doors in the Southeast and Southwest classrooms. The 5 year old room had paper covering the door. These items must not be blocking the exit.**

**\*Curtains and paper coverings have been removed as of 03/07/2019.**

Agency Action:

**Compliance Plan**

Suggested  
Completion  
Date:

**03/20/2019**

Actual  
Completion  
Date:

**03/07/2019**

Status: **Corrected**

**Beth Hanna**

Provider Signature

**03/07/2019**

Date

**Clint Rux**

Inspector Signature

**03/07/2019**

Date