## **Facility Safety Inspection** Fire & Life Safety / Environmental Health **Before & After School Center - School Location Compliance Plan**

Provider's Name:	EmBe Harrisburg Fre	edom OST	City:	Harrisburg	Provider Number:	018042556
Inspector:	Jennifer Preuninger	Date of Inspec	ction:	09/18/2018	Time of Inspection:	2:54 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

1. Are written emergency evacuation plans posted? 67:42:14:28

Corrections To Be Made:	Agency Action:		
Evaucation plans to be posted at the facility.	Compliance Plan	n	
*Plans for fire as well as tornado evacation were posted on 09/20/18.	Suggested Completion Date:	Actual Completion Date:	
	09/20/2018	09/21/2018	
	Status: Correcte	Status: Corrected	

Ann Marie Gustafson

09/18/2018

Jennifer Preuninger

09/18/2018

**Provider Signature** 

Date

Inspector Signature

Date