Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - School Location Compliance Plan

Provider's Name: EmBe Harrisburg Endeavor City: Sioux Falls Provider Number: 018042663

OST

Inspector: Elijah Ehresmann Date of Inspection: 05/07/2019 Time of Inspection: 3:23 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

3. Is the fire alarm system operable? 61:15:05:08

Corrections To Be Made: Agency Action:

Recent inspection paperwork was not available at the time of DPS

inspection. *Copy of inspection received on 05/09/2019.

Compliance Plan

Suggested Actual
Completion Completion
Date: Date:

06/07/2019 05/09/2019

Status: Corrected

B. ENVIRONMENTAL HEALTH

17. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made:	Agency Action:		
Inspection paperwork was not available at time of state inspection. *Copy of maintenance and inspection document received on 05/09/2019.	Compliance Plan		
	Suggested Completion Date:	Actual Completion Date:	
	06/07/2019	05/09/2019	
	Status: Corrected		

C. FOOD SERVICE

40. Is tableware, equipment and utensils cleaned by use of a commercial dishwasher, a home-style dishwasher, or a manual wash/rinse/sanitize method? 67:42:11:07

*Staff reminded to use	de: canitizing step during dishwashing process. se appropriate sanitizing process moving forward te items. Procedure will be monitored by the program		Agency Action: Compliance Plan Suggested Actual	
director.	tems. Procedure will be mor	intored by the program	Completion Date: 06/07/2019	Completion Date: 05/09/2019
			Status: Correct	ed
e Jorgensen	05/07/2019	Elijah Ehresma	ann	05/07/2019
rider Signature	Date	Inspector Signa	ature	Date