

# Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Hand In Hand Community Daycare**

City: **Miller**

Provider Number: **000097047**

Inspector: **Brenda Sharkey**

Date of Inspection: **11/13/2019**

Time of Inspection: **2:42 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

<p>Corrections To Be Made:</p> <p><b>Exit doors from infant area need the dead bolt locks removed.</b></p> <p><b>The dead bolt locks have been removed from the exit doors in the infant area.</b></p>	<p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>11/29/2019</b></td> <td style="text-align: center;"><b>11/26/2019</b></td> </tr> </table> <p>Status: <b>Corrected</b></p>	Suggested Completion Date:	Actual Completion Date:	<b>11/29/2019</b>	<b>11/26/2019</b>
Suggested Completion Date:	Actual Completion Date:				
<b>11/29/2019</b>	<b>11/26/2019</b>				

**Clover Herdman**

Provider Signature

**11/13/2019**

Date

**Brenda Sharkey**

Inspector Signature

**11/13/2019**

Date