Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name:	First Baptist Childre	n's Center	City:	Sioux Falls	Provider Number:	010602017
Inspector:	Dwight Johnson	Date of Inspec	ction:	04/12/2019	Time of Inspection:	1:00 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

11. Are exit signs provided over each exit, and where necessary to identify a change in the direction of egress travel? 61:15:05:05 NOTE: Exit signs must be interior or exterior illuminated or self-luminous.

Corrections To Be Made:	Agency Action:		
The exit sign in the nap room is not operational.	Compliance Plan	Compliance Plan	
Correction: The exit sign is operational.	Suggested Completion Date:	Actual Completion Date:	
	05/12/2019	05/10/2019	
	Status: Correcte	Status: Corrected	

B. ENVIRONMENTAL HEALTH

22. Does the construction of walls, ceilings, doors, window and skylights appear clean and in good repair? Does outside appearance and construction appear in good repair? 67:42:11:39

food pantry has a large hole. The wall must be repaired. Compliance Pla	n	
e wall in the food pantry is in good repair. Suggested Completion Date:	Actual Completion Date:	
05/12/2019	05/10/2019	
Status: Correct	Status: Corrected	
	-	

C. FOOD SERVICE

76. Is food free from spoilage or contamination and safe for human consumption? 67:42:11:16

Corrections To Be Made:	Agency Action:	
Correction: The paint roller was removed from the food prep area.	Compliance Plan Suggested Completion Date: 04/13/2019 Status: Corrected	Actual Completion Date: 04/13/2019

Sheena Christensen	04/12/2019	Dwight Johnson	04/12/2019
Provider Signature	Date	Inspector Signature	Date