

# Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Wagner Early Childhood Center** City: **Wagner**

Provider Number: **010603037**

Inspector: **Kenneth Anderson**

Date of Inspection: **05/18/2020**

Time of Inspection: **11:15 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

<p>Corrections To Be Made:</p> <p><b>There combustible items are stored less than 24 inches from the ceiling.</b></p> <p><b>*Combustible items were moved so that they are located at least 2 feet below the ceiling and program will assure that correct storage is maintained going forward.</b></p>	<p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>05/20/2020</b></td> <td style="text-align: center;"><b>05/20/2020</b></td> </tr> </table> <p>Status: <b>Corrected</b></p>	Suggested Completion Date:	Actual Completion Date:	<b>05/20/2020</b>	<b>05/20/2020</b>
Suggested Completion Date:	Actual Completion Date:				
<b>05/20/2020</b>	<b>05/20/2020</b>				

**Pauela Beeson**

Provider Signature

**05/18/2020**

Date

**Kenneth Anderson**

Inspector Signature

**05/18/2020**

Date