

Family Day Care Inspection Compliance Plan

Provider's Name: **Tamara Dixon**

City: **Sioux Falls**

Provider Number: **010605634**

Inspector: **Dwight Johnson**

Date of Inspection: **07/29/2019**

Time of Inspection: **8:08 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

C. Health & Safety Features of the Home - Indoor Environmental Observations

69. Is the hot water temperature at hand washing sinks maintained at 120 degrees or lower?
67:42:03:11.05

<p>Corrections To Be Made:</p> <p>Water temperature in the bathroom hand sink measured at 142 degrees F, must be 120 degrees or below. Adjust water temperature or install scald guard.</p> <p>*Water temperature tested at 120 degrees.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">08/16/2019</td> <td style="text-align: center;">08/15/2019</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	08/16/2019	08/15/2019
Suggested Completion Date:	Actual Completion Date:				
08/16/2019	08/15/2019				

Tamara Dixon

Provider Signature

07/29/2019

Date

Dwight Johnson

Inspector Signature

07/29/2019

Date