

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Apple Tree West**

City: **Sioux Falls**

Provider Number: **010605674**

Inspector: **Ron Werner**

Date of Inspection: **06/26/2018**

Time of Inspection: **11:13 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

| | | | | | |
|---|---|----------------------------|-------------------------|-------------------|-------------------|
| <p>Corrections To Be Made:</p> <p>Room E08 has an exit that was deadbolt locked. Deadbolt to be removed and panic hardware to be installed on each exit.</p> | <p>Agency Action:</p> <p>Letter of Notification</p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">07/26/2018</td> <td style="text-align: center;">10/16/2018</td> </tr> </table> <p>Status: Corrected</p> | Suggested Completion Date: | Actual Completion Date: | 07/26/2018 | 10/16/2018 |
| Suggested Completion Date: | Actual Completion Date: | | | | |
| 07/26/2018 | 10/16/2018 | | | | |

Toni Wiseley

Provider Signature

06/26/2018

Date

Ron Werner

Inspector Signature

06/26/2018

Date