

# Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Abiding Savior Under Christ's Care**      City: **Sioux Falls**

Provider Number: **010605802**

Inspector: **Elijah Ehresmann**      Date of Inspection: **10/01/2020**

Time of Inspection: **2:33 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

<p>Corrections To Be Made:</p> <p><b>The exit corridor in the auditorium is blocked by chairs.</b></p> <p><b>The exits and exit corridors must be maintained in a safe manner.</b></p> <p><b>Correction: The chairs were immediately removed from the exit corridor at the time of the inspection. Program staff will ensure that all exits/corridors are always maintained in a safe manner.</b></p>	<p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>10/01/2020</b></td> <td style="text-align: center;"><b>10/01/2020</b></td> </tr> </table> <p>Status: <b>Corrected Immediately</b></p>	Suggested Completion Date:	Actual Completion Date:	<b>10/01/2020</b>	<b>10/01/2020</b>
Suggested Completion Date:	Actual Completion Date:				
<b>10/01/2020</b>	<b>10/01/2020</b>				

Faye Fisher  
Provider Signature

10/01/2020  
Date

Elijah Ehresmann  
Inspector Signature

10/01/2020  
Date