

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Children's Care Corner**

City: **Howard**

Provider Number: **010605880**

Inspector: **Dwight Johnson**

Date of Inspection: **03/21/2019**

Time of Inspection: **1:30 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

<p>Corrections To Be Made:</p> <p>Decorations suspended from the ceiling in the pre-school room are not at least 24" from said ceiling. They must be suspended with nylon string to enable disintegration in case of a fire.</p> <p>*Some decorations were removed and others rehung at appropriate height with nylon string.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">03/28/2019</td> <td style="text-align: center;">03/21/2019</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	03/28/2019	03/21/2019
Suggested Completion Date:	Actual Completion Date:				
03/28/2019	03/21/2019				

B. ENVIRONMENTAL HEALTH

50. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made:

Annual heating/cooling inspection report was not able to be produced upon this time of inspection completion.

***An inspection was completed on 04/26/2019.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

Actual
Completion
Date:

04/21/2019

04/26/2019

Status: **Corrected**

Lea Selken

Provider Signature

03/21/2019

Date

Dwight Johnson

Inspector Signature

03/21/2019

Date