

Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - Non-School Location Compliance Plan

Provider's Name: **Ipswich Tiger Post CEC Inc.** City: **Ipswich** Provider Number: **011100998**
 Inspector: **Clint Rux** Date of Inspection: **08/20/2019** Time of Inspection: **12:45 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

11. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

<p>Corrections To Be Made:</p> <p>A storage shelf was placed in the width of the Northwest Exit on the main level. This must not be in the width of the exit.</p> <p>The shelf was moved out of the exit path and the exit path is clear.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">08/21/2019</td> <td style="text-align: center;">08/20/2019</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	08/21/2019	08/20/2019
Suggested Completion Date:	Actual Completion Date:				
08/21/2019	08/20/2019				

Madeline Miller

 Provider Signature

08/20/2019

 Date

Clint Rux

 Inspector Signature

08/20/2019

 Date