Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - School Location Compliance Plan

Provider's Name: Summit 21st CCLC City: Summit Provider Number: 011102468

Date of Inspection: 02/13/2020

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Time of Inspection: 11:03 AM

A. FIRE AND LIFE SAFETY

Inspector: Kelly Gnat

4. Are exit signs provided over each exit, and where necessary to identify a change in the direction of egress travel? 61:15:05:05 NOTE: Exit signs must be interior or exterior illuminated or self-luminous.

			Status: Corre	cted
			02/27/2020	02/17/2020
Several exit signs in the old side of the building where the located were not illuminated or self-luminous. The exit signs were serviced and all operational.			Completion Date:	Completion Date:
		nere the OST Program is	Compliance Plan Suggested Actual	
Corrections to be made	Corrections To Be Made:		Agency Action:	