

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Montessori School of Aberdeen Inc.** City: **Aberdeen**

Provider Number: **011102504**

Inspector: **Clint Rux**

Date of Inspection: **09/10/2019**

Time of Inspection: **1:35 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

10. If providing care for children under 5 years of age, are there self-closing, or tamper resistant childproof electrical covers on all outlets? 67:42:11:10

<p>Corrections To Be Made:</p> <p>Outlets in the gym, and toddler room next to the gym do not have self-closing outlet.</p> <p>Self-closing outlets were installed in the gym and the toddler room next to the gym.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">10/10/2019</td> <td style="text-align: center;">09/27/2019</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	10/10/2019	09/27/2019
Suggested Completion Date:	Actual Completion Date:				
10/10/2019	09/27/2019				

Susan Dalager

Provider Signature

09/10/2019

Date

Clint Rux

Inspector Signature

09/10/2019

Date