

Facility Safety Inspection

Fire & Life Safety / Environmental Health

Before & After School Center - School Location

Compliance Plan

Provider's Name: **SDSU OST Program**

City: **Brookings**

Provider Number: **011515519**

Inspector: **Charles Schmidt**

Date of Inspection: **01/31/2019**

Time of Inspection: **2:50 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

5. Are exits and exit corridors maintained in a safe manner; corridor widths must be maintained; exits are not be obstructed in any manner? 61:15:05:05

Corrections To Be Made:

Clear snow from exit door in art room.

****Snow cleared from exit door.****

Agency Action:

Compliance Plan

Suggested
Completion
Date:

02/07/2019

Actual
Completion
Date:

02/07/2019

Status: **Corrected**

Laura Gloege

Provider Signature

01/31/2019

Date

Charles Schmidt

Inspector Signature

01/31/2019

Date