Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - School Location Compliance Plan

Provider's Name:	Tiger After School P Buchanan	rogram - City	Huron	Provider Number:	014512233
Inspector:	Kelly Gnat	Date of Inspection	09/23/2019	Time of Inspection:	4:53 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

24. Is onsite, outside playground equipment maintained in good repair? 67:42:11:15

Corrections To Be Made:	Agency Action:	
The teeter totter is broken. It is taped off from usage and the school is aware. *Repairs were completed to the equipment.	Compliance PlanSuggestedActualCompletionCompletionDate:Date:	
	10/23/2019	10/30/2019
	Status: Corrected	

25. Is the outside play area free from unsafe obstacles or conditions that have potential to cause injury or be life-threatening to children? 67:42:11:02.01

Corrections To Be Made:	Agency Action:		
There is an area of fencing that is out of shape and not level with the ground in the far right corner of the playground.	Compliance Plan		
It should also be noted that the gate to the back parking lot was open at the time of my inspection and kids were on the playground with	Suggested Completion Date:	Actual Completion Date:	
supervision. *Repairs were completed to the fence and the Provider will assure that the	10/23/2019	11/20/2019	
gate is closed when children are outside playing going forward.	Status: Corrected		

Dawn Daugherty

Provider Signature

09/23/2019

Date

Kelly Gnat

Inspector Signature

09/23/2019

Date