## Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - School Location Compliance Plan

City: Huron

Provider Number: 014512235

Provider's Name: Tiger After School Program-

ashington				
int Rux	Date of Inspection:	09/24/2019	Time of Inspection:	3:40 PM
Provid	er was found t	o be in full complian	ce	
		•		
N9 <i>/</i> :	24/2019	Clint Rux		09/24/2019
	int Rux	int Rux Date of Inspection:	int Rux Date of Inspection: 09/24/2019	