

# Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - Non-School Location Compliance Plan

Provider's Name: **Oahe YMCA**

City: **Pierre**

Provider Number: **015500848**

Inspector: **Jennie Halajian**

Date of Inspection: **11/07/2018**

Time of Inspection: **4:08 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## B. ENVIRONMENTAL HEALTH

31. Is water temperature at children's hand washing sinks maintained at 120 degrees or lower?  
67:42:11:09

<p>Corrections To Be Made:</p> <p><b>Temperature at sink in women's bathroom is 138.5 F. Water needs to be turned down to be under 120 F.</b></p> <p><b>CORRECTION: A new boiler system has been installed and the water temperature is maintained at or below 120 F.</b></p>	<p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>12/07/2018</b></td> <td style="text-align: center;"><b>11/26/2018</b></td> </tr> </table> <p>Status: <b>Corrected</b></p>	Suggested Completion Date:	Actual Completion Date:	<b>12/07/2018</b>	<b>11/26/2018</b>
Suggested Completion Date:	Actual Completion Date:				
<b>12/07/2018</b>	<b>11/26/2018</b>				

**Lisa Maunu**

**11/07/2018**

Provider Signature

Date

**Jennie Halajian**

**11/07/2018**

Inspector Signature

Date