

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Bethesda Lutheran Church** City: **Hot Springs** Provider Number: **016597902**
 Inspector: **Jennifer Preuninger** Date of Inspection: **05/23/2018** Time of Inspection: **9:48 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

44. Is the water temperature at children's hand washing sinks maintained at 120 degrees or lower?
67:42:11:09

<p>Corrections To Be Made:</p> <p>Hot water temperature is currently to high, The hot water needs to be at 120 degrees or below.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">05/25/2018</td> <td style="text-align: center;">05/23/2018</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	05/25/2018	05/23/2018
Suggested Completion Date:	Actual Completion Date:				
05/25/2018	05/23/2018				

Ken Palmreuter

Provider Signature

05/23/2018

Date

Jennifer Preuninger

Inspector Signature

05/23/2018

Date