## Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - School Location Compliance Plan

Provider's Name: Douglas Schools - Vandenburg City: Box Elder Provider Number: 016599291

Inspector: Terra Robbins Date of Inspection: 01/29/2019 Time of Inspection: 3:35 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## **B. ENVIRONMENTAL HEALTH**

a Allen	01/29/2019	Terra Robbins			01/29/2019	
			Status:	Corrected		
inspection for verification	The inspection must be completed annually and avinspection.  *Program provided the documentation of the heatir inspection for verification.		02/05/2019		02/11/2019	
inspection. *Program provided th			Suggest Complet Date:		Actual Completion Date:	
	Program had no documentation of annual heating and cooling inspection.			Compliance Plan		
Corrections To Be Mad	Corrections To Be Made:			Agency Action:		