Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - School Location Compliance Plan

Provider's Name:	Douglas Schools - Va	andenburg	City:	Box Elder	Provider Number:	016599291
Inspector:	Terra Robbins	Date of Inspe	ction:	10/20/2020	Time of Inspection:	2:48 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

17. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made:	Agency Action:	
Program did not have documentation that the heating and cooling unit had been inspected annually. Heating and cooling units must be inspected annually and the program must have documentation on file.	Compliance Plan Suggested Completion	Actual Completion
*The program emailed verification that the heating and cooling systems had been inspected.	Date:	Date: 10/28/2020
	Status: Corrected	

Lisa Allen	10/20/2020	Terra Robbins	10/20/2020
Provider Signature	Date	Inspector Signature	Date