

Facility Safety Inspection

Fire & Life Safety / Environmental Health

Licensed Day Care Programs

Compliance Plan

Provider's Name: **Peace C.A.R.E.**

City: **Sioux Falls**

Provider Number: **018037458**

Inspector: **Stacy Wildermuth**

Date of Inspection: **01/08/2019**

Time of Inspection: **12:00 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:

Sprinkler heads in the closet of the Froggies room do not have 18 inches of clearance from combustible materials. Sprinkler heads in the storage area in the fellowship hall also need to have 18 inches of clearance around the sprinkler heads.

Combustible materials have been removed.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

02/08/2019

Actual
Completion
Date:

02/07/2019

Status: **Corrected**

Tara Foley

Provider Signature

01/11/2019

Date

Stacy Wildermuth

Inspector Signature

01/11/2019

Date