

# Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Inter Lakes Com. Action - Sioux Falls**      City: **Sioux Falls**

Provider Number: **018038755**

Inspector: **Kenneth Anderson**

Date of Inspection: **01/14/2019**

Time of Inspection: **12:27 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

<p>Corrections To Be Made:</p> <p><b>In room #7 there are combustible materials on the walls and ceiling fan less than 24 inch's from the ceiling. Items removed at the time of the inspection.</b></p>	<p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>01/17/2019</b></td> <td style="text-align: center;"><b>01/14/2019</b></td> </tr> </table> <p>Status: <b>Corrected Immediately</b></p>	Suggested Completion Date:	Actual Completion Date:	<b>01/17/2019</b>	<b>01/14/2019</b>
Suggested Completion Date:	Actual Completion Date:				
<b>01/17/2019</b>	<b>01/14/2019</b>				

Jenny Meinert  
Provider Signature

01/14/2019  
Date

Kenneth Anderson  
Inspector Signature

01/14/2019  
Date