

Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - Non-School Location Compliance Plan

Provider's Name: **Kidstop**

City: **Sioux Falls**

Provider Number: **018042497**

Inspector: **Kenneth
Anderson**

Date of Inspection: **10/29/2018**

Time of Inspection: **3:42 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

14. Is electrical system being used properly? 61:15:01 NOTE: Check for overloads or frayed extension cords.

<p>Corrections To Be Made:</p> <p>In room 304 there is a 3-way plug-in, plugged into a 2 plug outlet. The 3-way is not surge protected and can not be used.</p> <p>*3-way plug-in no longer used.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table border="0"> <tr> <td style="text-align: center;">Suggested Completion Date:</td> <td style="text-align: center;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">10/30/2018</td> <td style="text-align: center;">10/30/2018</td> </tr> <tr> <td colspan="2" style="text-align: center;">Status: Corrected</td> </tr> </table>	Suggested Completion Date:	Actual Completion Date:	10/30/2018	10/30/2018	Status: Corrected	
Suggested Completion Date:	Actual Completion Date:						
10/30/2018	10/30/2018						
Status: Corrected							

B. ENVIRONMENTAL HEALTH

25. Are children's hands washed before and after meals, and after using the restroom? 67:42:11:33

Corrections To Be Made:

It was observed that children did not wash there hands after the meal.

***Children now wash hands after every meal.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

10/30/2018

Actual
Completion
Date:

10/30/2018

Status: **Corrected**

Kassidi Smith

Provider Signature

10/29/2018

Date

Kenneth Anderson

Inspector Signature

10/29/2018

Date