

Facility Safety Inspection

Fire & Life Safety / Environmental Health

Licensed Day Care Programs

Compliance Plan

Provider's Name: **Snicklefritz on Sycamore**

City: **Sioux Falls**

Provider Number: **018042559**

Inspector: **Dwight Johnson**

Date of Inspection: **06/24/2019**

Time of Inspection: **1:00 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

37. Are toilet rooms and fixtures clean and in good repair? 67:42:11:06

Corrections To Be Made:

The bathrooms upstairs have wall sheetrock damage in certain areas. The hanging lightbulb in the first bathroom to the left up the stairway is not protected.

***Wall repaired and light fixture installed as of 08/20/19**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

07/24/2019

Actual
Completion
Date:

08/20/2019

Status: **Corrected**

41. Is each bathroom provided with natural or mechanical ventilation? 67:42:11:06

Corrections To Be Made:

The first bathroom up the stairs and to the left does not have a working fan vent.

***Fan operational as of 08/20/19**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

07/24/2019

Actual
Completion
Date:

08/20/2018

Status: **Corrected**

Miranda Rogers

Provider Signature

06/24/2019

Date

Dwight Johnson

Inspector Signature

06/24/2019

Date