Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - Non-School Location Compliance Plan

Provider's Name: Doodlebugs & Dinosaurs OST City: Brandon Provider Number: 018042582

Inspector: Elijah Ehresmann Date of Inspection: 01/08/2020 Time of Inspection: 3:25 PM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

21. Does the construction of walls, ceilings, doors, window and skylights appear clean and in good repair? 67:42:11:39

Corrections To Be Made:

Agency Action:

There is a hole in the wall of the media room exposing insulation. This hole should be repaired.

Compliance Plan

*Hole repaired as of 02/07/20.

Suggested Completion

Actual Completion Date:

Date:

02/08/2020

02/07/2020

Status: Corrected

27. Are toilet rooms and fixtures clean and in good repair? 67:42:11:06

Corrections To Be Made:

Agency Action:

The women's restroom was out of order due to plumbing issues.

Compliance Plan

*Repair observed as of 01/31/20.

Suggested Completion Date:

Actual Completion Date:

02/08/2020

01/31/2020

Status: Corrected

39. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made: Agency Action: **Compliance Plan** A current heating/cooling inspection report was not available at time of state inspection.
*Inspection completed on 01/23/2020. Suggested Completion Actual Completion Date: Date: 02/08/2020 01/23/2020 Status: Corrected 01/08/2020 **Erinn Schape** 01/08/2020 Elijah Ehresmann

Inspector Signature

Date

Date

Provider Signature