

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Good Shepherd Early
Childhood**

City: **Sioux Falls**

Provider Number: **018042612**

Inspector: **Dwight Johnson**

Date of Inspection: **04/01/2019**

Time of Inspection: **2:00 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

22. Does the construction of walls, ceilings, doors, window and skylights appear clean and in good repair?
Does outside appearance and construction appear in good repair? 67:42:11:39

Corrections To Be Made:

**Walls in several classrooms to be in good repair. Exhaust fans in
restrooms to be cleaned.
*Walls repaired and vents cleaned throughout the facility. Observed on
05/01/19.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

05/01/2019

Actual
Completion
Date:

05/01/2019

Status: **Corrected**

Lizz Jensen

Provider Signature

04/01/2019

Date

Dwight Johnson

Inspector Signature

04/01/2019

Date