

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Kids Crossing**

City: **Beresford**

Provider Number: **018042787**

Inspector: **Kenneth
Anderson**

Date of Inspection: **08/20/2018**

Time of Inspection: **7:54 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

<p>Corrections To Be Made:</p> <p>In the laundry room there are totes stored less than 2 feet from the ceiling.</p> <p>*The combustible items in the laundry room have been moved so there is a 24" clearance from the ceiling.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">08/24/2018</td> <td style="text-align: center;">08/22/2018</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	08/24/2018	08/22/2018
Suggested Completion Date:	Actual Completion Date:				
08/24/2018	08/22/2018				

Christina Quartier

08/20/2018

Kenneth Anderson

08/20/2018

Provider Signature

Date

Inspector Signature

Date