

Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - Non-School Location Compliance Plan

Provider's Name: **YMCA Youth Performance Center**

City: **Sioux Falls**

Provider Number: **018042829**

Inspector: **Dwight Johnson**

Date of Inspection: **02/26/2019**

Time of Inspection: **4:30 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

39. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

<p>Corrections To Be Made:</p> <p>Heating and cooling system inspection not able to be produced upon request at inspection time. *Inspection documents observed on 03/06/2019.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">03/26/2019</td> <td style="text-align: center;">03/06/2019</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	03/26/2019	03/06/2019
Suggested Completion Date:	Actual Completion Date:				
03/26/2019	03/06/2019				

Sarah Skarski

02/26/2019

Provider Signature

Date

Dwight Johnson

02/26/2019

Inspector Signature

Date