Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name:	His Ark Christian Ch Development Center		Sioux Falls	Provider Number:	018042862
Inspector:	Ron Werner	Date of Inspection:	06/27/2018	Time of Inspection:	10:49 AM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

Corrections To Be Made:	Agency Action:	
The emergency light is not working by Frogs room.	Compliance Plan	
	Suggested Completion Date:	
	07/27/2018	08/17/2018
	Status: Corrected	

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:	Agency Action:		
Storage items need to be stored at least18 inches below sprinkler head in the gym storage room, art room, and some bathrooms.	Compliance Plan		
the gym storage room, art room, and some bath coms.	Suggested Completion Date:	Actual Completion Date:	
	07/11/2018	08/17/2018	
	Status: Corrected		

Jodene Baker

Provider Signature

06/27/2018

Date

Ron Werner

Inspector Signature

06/27/2018

Date