## Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name:	Melissa's Little Lamb	os City:	Parker	Provider Number:	018042907
Inspector:	Lara Kvale	Date of Inspection:	03/01/2018	Time of Inspection:	9:08 AM

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

 In Licensed Day Care Programs Caring for 21 or More Children - Is a fire alarm system installed in the building wiring and operable? 61:15:05:08 NOTE: Manual pull stations, audible alarms inside and out. Smoke detectors are in stairwells, corridors, lounges, recreation and sleeping areas.

Corrections To Be Made:	Agency Action:	
The fire alarm system has not been inspected. The display shows a trouble warning. Staff have ordered a part to fix the trouble warning. Have the system inspected and address any warning lights on the system immediately.	Compliance Plan	
	Suggested Completion Date:	Actual Completion Date:
	04/01/2018	04/04/2018
	Status: Corrected	

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

Corrections To Be Made:	Agency Action:	
The North exit door that leads to the playground has snow/ice built up outside, which does not allow the door to open fully. Remove the snow and ice so the door can open completely.	Compliance Plan	
	Suggested Completion Date:	Actual Completion Date:
	04/01/2018	04/04/2018
	Status: Corrected	I

18. Are portable fire extinguishers charged and operable? 61:15:05:10 NOTE: Minimum 2A rated on each level. No more than 75 feet travel distance to an extinguisher. One near food preparation.

Corrections To Be Made:	Agency Action:	
The fire extinguisher in the kitchen is sitting on the floor. It needs to be mounted to the wall.	Compliance Plan	
	Suggested Completion Date:	Actual Completion Date:
	04/01/2018	04/04/2018
	Status: Corrected	

## **B. ENVIRONMENTAL HEALTH**

22. Does the construction of walls, ceilings, doors, window and skylights appear clean and in good repair? Does outside appearance and construction appear in good repair? 67:42:11:39

Corrections To Be Made:	Agency Action:	
The front (east) door is made of glass and is cracked. Have the glass or the entire door replaced so it is in good repair.	Compliance PlanSuggestedActualCompletionCompletion	
	Date:	Date:
	04/01/2018	04/04/2018
	Status: Corrected	

50. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made:	Agency Action:		
The heating system has been inspected, but the cooling system has not. Have the cooling system inspected annually.	Compliance Plan		
	Suggested Completion Date:	Actual Completion Date:	
	04/01/2018	04/04/2018	
	Status: Corrected	ł	

70. NEW PROGRAMS: Are all requirements identified in the floor plan review letter issued by the Department of Health completed? Does facility layout match the approved floor plan? 67:42:10:17

Corrections To Be Made:	Agency Action:	
The dryer has not been hooked up yet and there is no venting to the outside installed. The dryer must be vented to the outside of the building.	Compliance Plan	
	Suggested Completion Date:	Actual Completion Date:
	04/01/2018	04/04/2018
	Status: Corrected	

Melissa Preheim Provider Signature 03/01/2018

Date

Lara Kvale	
Inspector Signature	

03/01/2018

Date