## Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - School Location Compliance Plan

Provider's Name: Andes Central After School City: Lake Andes Provider Number: Program	019525353
Inspector: Kenneth Date of Inspection: 10/09/2019 Time of Inspection: Anderson	3:36 PM
Provider was found to be in full compliance	
Judy Naatz     10/09/2019     Kenneth Anderson       Provider Signature     Date     Inspector Signature	<b>10/09/2019</b> Date